

Next text 75% black: Graywedge 1 should be printed by rich black CMYK. Graywedge 2 by K-only. Graywedge 1 has always a tint until the printer is accurately color calibrated. The three CMY wedges should be printed by pure inks. Next text 100% black: Source working space for RGB components was sRGB. Artefacts may appear in the PDF preview if Smooth Line Art is enabled in Acrobat.

